

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h1 style="text-align: center;">AlisonK - Arboriculture</h1> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
1	Quercus robur (English Oak)	15.0m	8.0m	40 + years	Mature	OVERALL CONDITION - Good No change in condition since last inspection	No significant safety issues	No action required	–	
2	Quercus robur (English Oak)	12.0m	6.0m	40 + years	Young	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
3	Pinus spp. (Pine spp)	18.0m	6.0m	10 + years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
4	Quercus robur (English Oak)	15.0m	9.0m	40 + years	Mature	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	–	
5	Pinus spp. (Pine spp)	18.0m	6.0m	10 + years	Fully-Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
6	Acer pseudoplatanus (Sycamore)	16.0m	10.0m	20+ years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
7	Acer pseudoplatanus (Sycamore)	16.0m	4.0m	10 + years	Maturing	OVERALL CONDITION Indifferent No change in condition since last inspection.	No significant safety issues	No action required	–	
8	Quercus robur (English Oak)	16.0m	10.0m	40 + years	Mature	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	–	
9	Acer pseudoplatanus (Sycamore)	–	–	–	–	Tree now felled as part of recommendation in last report in 2022	–	No action required	–	
10	Acer pseudoplatanus (Sycamore)	–	–	–	–	Tree now felled as part of recommendation in last report in 2022	–	No action required	–	
11	Pinus spp. (Pine spp)	18.0m	6.0m	10 + years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
12	Acer pseudoplatanus (Sycamore)	19.0m	8.0m	10 + years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
13	Quercus robur (English Oak)	15.0m	7.0m	40 + years	Mature	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	–	

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h1 style="text-align: center;">AlisonK - Arboriculture</h1> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
14	Pinus spp. (Pine spp)	18.0m	6.0m	10 + years	Mature	OVERALL CONDITION - Fair Tree crown remains healthy although stem lean significant and over neighbouring garden.	Angle of stem lean may have increased slightly since last inspection however no evidence of ground movement on upper side of stem and root system shared and supported with large adjacent sycamore (16). No significant safety issues.	No action required	—	
15	Castanea sativa (sweet chestnut)	7.0m	8.0m	40 + years	Young	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	—	
16	Acer pseudoplatanus (Sycamore)	16.0m	9.0m	20+ years	Mature	OVERALL CONDITION- Good No change in condition since last inspection.	No significant safety issues	No action required	—	
17	Pinus spp. (Pine spp)	18.0m	6.0m	10 + years	Fully-Mature	Tree has been felled since last inspection. Reason not known. Replacement planting needed to maintain tree cover in the long term.	replant with new pine tree.	No action required	—	
18	Acer pseudoplatanus (Sycamore)	14.0m	5.0m	20+ years	Maturing	OVERALL CONDITION - Good No change in condition since last inspection. Good structured young tree with at least 40mm diameter growth to fence. Resist work if it is requested as lack of trees is already degrading amenity with long stretch of 6ft fence prominent.	No significant safety issues	No action required	—	
19	Acer pseudoplatanus (Sycamore)	—	—	—	—	Tree now removed. only low stump remains. Reason for removal not known, possibly due to close proximity to fence.	—	No action required	—	
20	Acer pseudoplatanus (Sycamore)	12.0m	6.0m	20+ years	Mature	OVERALL CONDITION - Poor No change in condition since last inspection. minor deadwood present. Not significant in terms of safety.	No significant safety issues	No action required	—	
21	Acer pseudoplatanus (Sycamore)	12.0m	8.0m	20+ years	Fully Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	—	
22	Acer pseudoplatanus (Sycamore)	14.0m	5.0m	40 + years	Young	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	—	
23	Acer pseudoplatanus (Sycamore)	—	—	—	—	Tree felled as part of past safety inspection.	—	No action required	—	

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h1 style="text-align: center;">AlisonK - Arboriculture</h1> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
24	Acer pseudoplatanus (Sycamore)	18.0m	11.0m	40 + years	Maturing	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	–	
25	Acer pseudoplatanus (Sycamore)	20.0m	6.0m	40 + years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
26	Acer pseudoplatanus (Sycamore)	14.0m	6.0m	20+ years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
27	Acer pseudoplatanus (Sycamore)	18.0m	10.0m	20+ years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
28	Acer pseudoplatanus (Sycamore)	18.0m	6.0m	20+ years	Maturing	OVERALL CONDITION Fair Most of the branches overhanging the care home which were cut back before the last inspection in 2022 have now died off	Dead branches are short stubs and not a safety issues.	No action required	–	
29	Acer pseudoplatanus (Sycamore)	18.0m	10.0m	40 + years	Maturing	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues	No action required	–	
30	Acer pseudoplatanus (Sycamore)	18.0m	10.0m	40 + years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
31	Fagus sylvatica (Common Beech)	17.0m	10.0m	10 + years	Fully-Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
32	Acer pseudoplatanus (Sycamore)	17.0m	10.0m	20+ years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection. Ivy getting more dense but management not necessarily at present. Water filled pocket note in previous inspection is shrinking as tree stem diameter increases.	No significant safety issues	No action required	–	
33	Acer pseudoplatanus (Sycamore)	17.0m	16.0m	20+ years	Mature	OVERALL CONDITION - Fair Regrowth from historic crown reduction is starting to get extensive. One piece of deadwood about 60mm diameter hung up in crown	Deadwood not large and well hung up in crown but needs removing. At same time, carry out climbing inspection to check historic pruning point branch attachment.	Remove hung up dead branch and carry out climbing inspection to check historic pruning point branch attachment.	Within 6 months	
34	Quercus cerris (Turkey Oak)	20.0m	10.0m	40 + years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	
35	Castanea sativa (Sweet Chestnut)	16.0m	11.0m	40 + years	Mature	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues	No action required	–	

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h1 style="text-align: center;">AlisonK - Arboriculture</h1> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
36	Quercus robur (English Oak)	18.0m	12.0m	40 + years	Veteran	<p style="text-align: center;">OVERALL CONDITION - Good</p> <p>Very large diameter Veteran pollard. Looks to be shared ownership. No access to inspect 360° as close border fence abuts both sides. No change in visible parts since last inspection</p>	No significant safety issues	No action required	—	
37	Fagus sylvatica (Common Beech)	23.0m	10.0m	40 + years	Mature	<p style="text-align: center;">OVERALL CONDITION - Good</p> <p>Just a skeleton of ivy left with structure now almost all visible. No defects evident. No change in condition since last inspection.</p>	No significant safety issues	No action required	—	
38	Acer pseudoplatanus (Sycamore)	20.0m	8.0m	20+ years	Mature	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>No change in condition since last inspection.</p>	No significant safety issues	No action required	—	
39	Acer pseudoplatanus (Sycamore)	20.0m	4.0m	20+ years	Mature	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>Ivy managed recently. Stem not yet visible but not likely to be masking defects. No change in condition since last inspection</p>	No significant	No action required	—	
40	Fagus sylvatica (Common Beech)	20.0m	10.0m	20+ years	Mature	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>No change in condition since last inspection. Lightly ivy clad, but not masking defects.</p>	No significant safety issues.	No action required	—	
41	Fagus sylvatica (Common Beech)	25.0m	12.0m	20+ years	Mature	<p style="text-align: center;">OVERALL CONDITION Good -</p> <p>No change in condition since last inspection.</p>	No significant safety issues.	No action required	—	
42	Castanea sativa (Sweet Chestnut)	20.0m	14.0m	20 + years	Mature	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>Inspected this tree a few months ago in summer of 2023. It is starting to loose vitality from tree top and sporadic deadwood was evident throughout, some up to 150mm.</p>	Tree would benefit from crown reduction whilst removing the deadwood. Would likely boost regrowth and extend life expectancy. (Not going to look pretty in short term)	Carry out crown reduction sides and top to reduce crown by up to 9m from height & 3 metres Leaving tree around 8 to 9 metres high.	Within 6 months	
43	Carpinus betulus (Hornbeam)	18.0m	10.0m	100+ Years	Maturing	<p style="text-align: center;">OVERALL CONDITION - Good</p> <p>No change in condition since last inspection.</p>	No significant safety issues.	No action required	—	
44	Acer pseudoplatanus (Sycamore)	18.0m	8.0m	20+ years	Young	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>No change in condition since last inspection</p>	No significant safety issues.	No action required	—	
45	Acer pseudoplatanus (Sycamore)	18.0m	8.0m	20+ years	Maturing	<p style="text-align: center;">OVERALL CONDITION - Fair</p> <p>No change in condition since last inspection.</p>	No significant safety issues.	No action required	—	
46	Castanea sativa (Sweet chestnut)	20.0m	10.0m	40 + years	Mature	<p style="text-align: center;">OVERALL CONDITION - Good</p> <p>No change in condition since last inspection. Branches lifted over garden since last inspection now clear to 4/5 metres from ground.</p>	No significant safety issues.	No action required	—	

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h1 style="text-align: center;">AlisonK - Arboriculture</h1> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
47	Acer pseudoplatanus (Sycamore)	17.0m	8.0m	20+ years	Maturing	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues.	No action required	–	
48	Carpinus betulus (Hornbeam)	18.0m	8.0m	100+ Years	Maturing	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues.	No action required	–	
49	Acer pseudoplatanus (Sycamore)	18.0m	6.0m	20+ years	Young	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues.	No action required	–	
50	Quercus robur (English Oak)	18.0m	8.0m	100+ Years	Young	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues.	No action required	–	
51	Betula pendula (Silver Birch)	14.0m	6.0m	40 + years	Maturing	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues.	No action required	–	
52	Carpinus betulus (Hornbeam)	7.0m	8.0m	100+ Years	Young	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues.	No action required	–	
53	Fraxinus excelsior (Common Ash)	11.0m	5.0m	10 + years	Young	OVERALL CONDITION - Fair No change in condition since last inspection.	No significant safety issues.	No action required	–	
54	Acer pseudoplatanus (Sycamore)	–	–	–	–	Tree now felled as part of recommendation in last report in 2022	–	No action required	–	
55	Acer pseudoplatanus (Sycamore)	11.0m	4.0m	> 5 years	Young	First individual inspection: OVERALL CONDITION - Dying Tree located within Gp1. It shows severe signs of sooty bark disease. Tree almost or completely dead.	Tree wood will become brittle fairly quickly after death once infected with sooty bark disease.	Fell tree to ground level and remove all arisings from site	Within 6 months	
56	Acer pseudoplatanus (Sycamore)	20.0m	7.0m	> 5 Years	Maturing	First individual inspection: CONDITION - Poor Part of Gp3. Tree showing signs of Kretzschmaria deusta (brittle cinder) at base. Not extensive yet but will likely spread through base over the next few years.	Tree not likely to be at risk of failure in the short term however, tree will not recover and could become unstable before the next inspection date.	Fell to ground level and remove all arisings from site.	Within 6 months	
57	Acer pseudoplatanus (Sycamore)	25.0m	10.0m	5+ Years	Fully Mature	First individual inspection: OVERALL CONDITION - Indifferent Part of Gp3. Twin stemmed from 1.2m. Union tight with included bark. Some adapted wood at union but no supporting natural bracing. Location of new care home adjacent has raised target making work necessary should stem fail it could impact on the care home.	Precautionary works needed to reduce weight and pressure on the potentially weak twin union at 1.2m.	Carry out crown reduction of up to 4m in height to reduce load on twin stem union.	Within 6 months	
58	Acer pseudoplatanus (Sycamore)	27.0m	15.0m	20 + years	Mature	First individual inspection: OVERALL CONDITION - Good Tree one of largest of the six sycamore trees in Gp4. Three moderate size dead branches in crown on main stem at 7 to 10 metres up.	Deadwood needs removing as located over footpath	Remove deadwood from crown at 7 to 10m up back to main stem.	Within 6 months	

Project:	Tree safety assessment Saxon Way					Surveyed by: Mrs Alice Martin-Butler		<h2 style="text-align: center;">AlisonK - Arboriculture</h2> <p style="text-align: center;">6 Pond Piece, Brandeston, Woodbridge, IP13 7AW T: 01728 685898 M: 07425389786 E: ali@alisonK.co.uk</p>		
Ref:	Appendix B7. REVIEW2: Schedule of trees, work recommendations & priority timescales.					Weather: Fine and dry.				
Survey Date:	1st & 2nd February 2024					Notes:				
Client:	Melton Parish Council					1: Comments and updates from latest survey are shown in blue. 2: Identifying trees for work on site: Trees have been marked with an orange spray mark discreetly at base of tree or on ivy stem. 3: Some trees contained in this schedule are covered by TPO 25.				
		Estimated (metres)								
Tree/Gp Number	Species	Height	Crown Spread	Life Expectancy (years)	Age Class.	Tree Problems/Comments.	Safety significance and recommendations	Work required on safety grounds	Work Priority	
G1	Mixed Broadleaves 15 x sycamore, holly, 1 x lural, 1 x yew and dense bramble.	-	-	40+ years	Young	OVERALL CONDITION Fair - No significant safety issues however some of the young sycamores appear to be declining in health and may need removing within a few years. One sycamore (56) added individually for felling following this inspection.	No significant safety issues.	No action required	-	
G2	Mixed Broadleaves. Mainly holly and yew	5.0m	-	40 + years	Young	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues.	No action required	-	
G3	Mixed Broadleaves. Inc sycamore, young elm & maturing holly.	-	-	-	Mixed	OVERALL CONDITION - Good No change in condition since last inspection.	No significant safety issues.	No action required	-	
G4	Acer pseudoplatanus (Sycamore)	25.0m	-	40 + years	Mature	OVERALL CONDITION - Good. As a group these trees remain prominent and impressive. One sycamore (58) has been added as an individual as some deadwood in the crown has been recorded.	No significant safety issues.	No action required	-	
G5	Mixed Broadleaves. mainly sycamore & field maple	15.0m	-	40 + years	Young	OVERALL CONDITION Good- Group remains in good condition. Longer term tree health would benefit from some active manage to thin 30% of sycamore stems.	No significant safety issues.	No action required	-	