


Item	Action Required	Action possible	Status
Gate 1	<ul style="list-style-type: none"> Ensure the gate closes between 4-8 seconds. 	<ul style="list-style-type: none"> Investigate if this can be achieved 	Not feasible
Gate 1	<ul style="list-style-type: none"> Opening between gate and post should be greater than 12mm 	<ul style="list-style-type: none"> Not feasible unless gates are changed 	Closed
Fencing	<ul style="list-style-type: none"> Reset loose posts Secure all loose fixings Monitor and repair damaged sections 	<ul style="list-style-type: none"> To be repaired 	Completed
Rotor Play - Supanova	<ul style="list-style-type: none"> Safety surface is damaged. Monitor and repair as required 	<ul style="list-style-type: none"> Fill with silicon 	Surface company advised better to cut out areas and fill with new surface rather than fill with silicon
Activity Equipment- Multi Play (Junior)	<ul style="list-style-type: none"> Remove moss/algae Secure loose fixings on dome Monitor rope covers as they are damaged/worn Monitor rope/nets for damage 	<ul style="list-style-type: none"> Spray algae Fix loose fixings on dome Will need replacing in next few years 	Sprayed In progress
Rotor Play- Spinner Bowl	<ul style="list-style-type: none"> Grass mats are silted and soil compacted. Are they impact absorbing? 	<ul style="list-style-type: none"> Would need digging out and replacing to fix properly 	
Swings- 2 Bay 4 Seat (Flat)	<ul style="list-style-type: none"> Treat rust and repaint Replace worn or missing bushes 	<ul style="list-style-type: none"> Repaint Check again in 2020 	
Rocking Equipment – See Saw	<ul style="list-style-type: none"> Remove algae/moss Treat rust and repaint Check if any repairs can be made to base of panel Replace missing or damaged bolt covers 	<ul style="list-style-type: none"> Spray Repaint Would need to replace whole unit Not necessary 	Sprayed
Free Standing Slide	<ul style="list-style-type: none"> Repair surfacing where there are gaps greater than 30mm Treat rust and repaint Repair dents if possible 	<ul style="list-style-type: none"> Fill with concrete Repaint Not possible to repair dents 	Closed
Swings 1 Bay 2 Seats (Cradle)	<ul style="list-style-type: none"> Repair gaps in surfacing 	<ul style="list-style-type: none"> Fill with concrete 	
Rotor Play - Roundabout	<ul style="list-style-type: none"> Treat rust and repaint Check if bearing needs replacing 	<ul style="list-style-type: none"> Consider replacing this item in the longer term. No repairs possible 	

Multi Use Games Area – Basketball Post	<ul style="list-style-type: none"> • Repair or replace hoop net • Repair eroded surface 	<ul style="list-style-type: none"> • Cost of replacing net is £220 • Not possible to repair surface 	Closed Closed
Multi Use Games Area – 5 a side Goals	<ul style="list-style-type: none"> • Repair/replace ropes and net • Remove weeds around edges • Treat rust and repaint 	<ul style="list-style-type: none"> • Tidy up edges. MUGA may be replaced this year 	Completed
Activity Equipment – Multi Play (Senior)	<ul style="list-style-type: none"> • Secure all loose fixings • Replace traveller and traveller guard if needed • Replace rotted timbers • Reset the spinning post socket • Replace/repair damaged ropes and nets • Grass mats are silted up which will make them slippery when wet. Reinstate as required 	<ul style="list-style-type: none"> • Investigate what is possible • Cost of replacing traveller guard is £116 • Monitor for further rotting • Dig out and reset • Monitor as not too bad • Leave for now – no action needed • Will spray the algae 	In progress Traveller guard replaced. Sprayed

The Committee is asked to decide what to do about the items that cannot be repaired, ie Seesaw and roundabout. The Playpot will not be replenished and future funding will only come from CIL or grants.



Pip Alder

Assistant Clerk & Management Officer

31st October 2019