



MELTON PARISH COUNCIL

REC(20)21.01

Melton Playing Field

Electricity Supply/Security Barrier

Confidential paper REC(20)33 relates to the purchase and installation of a security barrier.

Drainage Ditch

The drainage ditch running behind the zip wire was cleared by SCL.

Drainage Issues near new picnic tables

The ground is very waterlogged between the tree near the picnic tables and the drainage ditch. This is a natural path used by walkers and some cyclists. Some remedial work may need to be carried out in the Spring.

Lower field

A quote has been sought from SCL to repair the ruts in the field that were caused when the tree safety work was carried out in November. They propose to fill in/level the rutted area on the lower field by bringing in approximately 2 tonnes of screened top soil and seed the areas. This will cost £165.00 + VAT.

Councillors are asked to:

- 1) Note and comment on this report
- 2) Agree if work to repair the ruts is required and if so, appoint SCL to carry out the work

Pip Alder
Asst Clerk and Management Officer
March 2020